

Mohawk Valley Water Authority Capital Improvement Program Marcy Reservoir Breaching

The Marcy Reservoir, in service from 1915 to 2011, has been replaced by a Water Storage Tank and is being decommissioned. This will result in the Reservoir being removed from the NYSDEC list of Regulated Dams and eliminate significant MVWA inspection and maintenance obligations.



First earthwork cut into the Reservoir Embankment. All work is being completed by MVWA crews.



Cutting the Reservoir Embankment. Note Erosion Control Fabric.



Placing cut material inside the Reservoir.



Near final elevation of new embankment grading.